

Eliminex Exterminators
 776 Jernee Mill Rd Unit 128
 732-284-3807 State Lic#97642A
 Sayreville NJ 08872
 Phone: 732-284-3807

ESTIMATE



www.newjerseypest.com/payment.html

Lic#26785A

Estimate #:	0000330
Date:	April 24, 2016
Estimate Total (USD):	\$6.96

Item	Description	Unit Cost (\$)	Quantity	Price (\$)
Attic Insulation Contamination Removal and Replace	Remove Soiled, Damaged, and Contaminated Insulation Batting and Replace with New R 30 Fiberglass Insulation Batting Apply Disinfectant, Sanitizer, and Virucide after cleanup and wait until dry before installing insulation batting Price Represents Per Square Foot *****OR*****	4.50 0.00	1 0	4.50 0.00
Clean Up / Sanitize / Deodorize	Clean up of Contaminated Attic Space, Crawlspace, Basement, Garage of Wildlife and Rodent Debris with Hepa Filter Vacuum and Apply DSV Virucide and Atomizing Deodorizer \$2 per Square Foot for Clean Up and Sanitizing / Deodorizing \$4.50 per Square Foot Insulation Removal, Sanitizing and Batting Insulation Replacement in Attic and Crawlspace Locations (Contaminated Section Areas Only) Inspector is required to suit up for breathing and contact protection in Bio-Hazard pathogen and rodent-borne illness environments such as Attics, Crawlspace, and Unfinished basements. A thorough visual inspection of the roof line and gutter / gable regions which also requires ladder work so all above Eliminex needs to charge for this specific type of inspection in order to correctly identify the problem nuisance wildlife and possibly uncover source of entry as well which is not guaranteed to find a source of entry through just an initial inspection.	2.00	1	2.00
NOTES: **Customers Initials_____**				
			Subtotal:	6.50
			New Jersey - 7%:	0.46
			Estimate Total (USD):	\$6.96

You can schedule by contacting our manager derekb_nj@hotmail.com or 732-284-3807
for an appointment